

LOCATION OF MEETING: 96 RUSSELL DRIVE

Meeting Minutes

- 1. Call to Order, Roll Call: Chairman San Felippo called the meeting to order at 6:05pm. Commission members present included Randy Soerens, Peter Lederer, Mike San Felippo, Jeff Schultz, and John Schluechtermann. Village employees present were Clerk/Treasurer Stephanie Waala. For additional attendees see attached sign in sheet.
- 2. Discussion and Possible Action on the approval of minutes from April 3, 2023 & May 1, 2023

Member Soerens made a motion to approve as submitted; motion was seconded by Member Schluechtermann. Motion carried 5-0.

3. Discussion and Possible Recommendation to the Village Board on the construction of an addition at 647 1st St

Member Schluechtermann asks for clarification as to on the plans it shows a deck, but on the survey it does not show. Property owner Brent Schicker informed the board the correct plan shows the deck and it was an error that it was not put on the survey.

Member Schluectermann made a motion to approve contingent that the survey be updated to include the deck; motion was seconded by Member Soerens. Motion carried 5-0.

4. Discussion and Possible Recommendation to the Village Board on the construction of a new home 190 E Shore Dr.

Member Schluechtermann asks for clarification on the gable overhangs as they are not showing dimensions on the plans. The front setback would need to be setback in order for the home to comply. Property owner Jake Reuteler informed the board the gable overhang is 1 foot.

Member Schluchtermann made a motion to approve contingent the house be setback approximately 9 inches to meet the front yard setbacks; motion was seconded by Member Soerens. Motion carried 5-0.

5. Adjourned at 6:21 pm



Architectural Review Board Meeting Monday, June 5, 2023 6:00 p.m.

Items on the Agenda may be taken out of order as listed. Posted to all village posting locations on 06/26/2023.





LOCATION OF MEETING: 96 RUSSELL DRIVE

Meeting Minutes

- 1. Call to Order, Roll Call: Chairman San Felippo called the meeting to order at 6:00pm. Commission members present included Mike San Felippo, Jeff Schultz, Barbara Ruege, Randy Soerens, Steve Masslich, and Peter Lederer. Village employees present were Clerk/Treasurer Stephanie Waala. For additional attendees see attached sign in sheet.
- 2. Discussion and Possible Recommendation to the Village Board on the construction of a garage addition at 89 E Shore Dr.

Contractor Dan Mondlach informed the board that the slab was installed last year. This year they would like to convert it into a 3 seasons room. This would not max out the buildings available square footage if an additional addition would like to added in the future.

Clerk Waala inquired as to the survey not showing the distance from the closest corner to the lot line. Contractor Mondlach informed the board the building would not be closer than 7 feet.

Member Soerens made a motion to approve as submitted; motion was seconded by Member Masslich. Motion carried 6-0.

3. Discussion and Possible Recommendation to the Village Board on the construction of a concession stand at 53 Russell Dr.

Chairman San Felippo informed the board this item is coming back because prior approval was too expensive to build and added \$20,000 over budget. A four foot overhang will be on the north and south side of the building.

Dale Krier inquired is it will be closer to the parking lot because of the park attendant. Chairman San Felippo informed the board that is still undetermined.

Member Ruege informed the board that the sole original purpose of the building was for the park attendant and now the view does not over look the lake or parking lot.

Member Lederer informed the board that with the current proposal it would be in the floodplain. It has not been determined if it can be moved west to be out of the floodplain.



Architectural Review Board Meeting Monday, June 19, 2023 6:00 p.m.

Member Masslich made a motion to approve as submitted, motion was seconded by Member Soerens. Motion carried 6-0.

4. Adjourned at 6:31 pm

Items on the Agenda may be taken out of order as listed. Posted to all village posting locations on 06/26/2023.





LOCATION OF MEETING: 96 RUSSELL DRIVE

Meeting Minutes

1. Call to Order, Roll Call: Chairman San Felippo called the meeting to order at 6:00pm. Commission members present included John Schluechtermann, Barbara Ruege, Jeff Schultz, Mike San Felippo, and Peter Lederer. Village employees present were Clerk/Treasurer Stephanie Waala. For additional attendees see attached sign in sheet.

Let it be known that there was a quorum of the Village Board as Trustee Duane Urbanski was present.

2. Discussion and Possible Recommendation to the Village Board on the reconstruction of a deck at 93 Hwy 144.

Chairman San Felippo informs the board of his concerns that the deck crosses over the property line onto the vacant parcel adjacent. These parcels are owned by the same individuals but are currently not combined.

Member Schluechtermann inquires to as if the original deck was permitted. Member Lederer pulled the property file and located the original permit from 1993, but it shows it as being within the lot lines.

Member Schluechtermann recommends the project be denied until the lots can be combined.

3. Discussion and Possible Recommendation to the Village Board on the reconstruction of signs at 201 Allen St.

Member Lederer informed the board that the project is replacement of current signs, the sizes are to remain the same.

Member Schluechtermann made a motion to approve as submitted, motion was seconded by Member Ruege. Motion carried 5-0.

4. Discussion and Possible Recommendation to the Village Board on the construction of a shed at 618 Spring Ct.

Chairman San Felippo informed the board that the request meets the requirements of the shed max square footage.

Member Lederer informed the board that it matches the design of the home, except there are no windows in the garage door.





P.O. Box 344 • 96 Russell Drive • Random Lake, WI 53075 Phone: (920) 994-4852 • Fax: (920) 994-2390

Building Permit Application

Job Location (identify e	xaci address) S	TREET			Permit#		
Owner's Name	MAHER_	Phone Number 920 226-1727	Contact's Name (When Relevant)			Phone Nu	ımber
Owners Address (if diffe	erent from above)	(60)-0 1121	City		State	Zip Code	
Contractor's Name		License Number	Contractor's Contact Name			Phone Nu	imber
Contractor's Address			City		State	Zip Cod	e
It is the respons	sibility of the perm	it holder to arrange for	r appointment times when entry if the work is not visible, a re-i	is avail	able for the r	equired inspect	ions If the
Use of Building	Type of Work		Item		Size/Qty.	Fee	Amount
☐ Residential	□ New	Residence (One &	t Two Family)			.30/sq. ft.	
☐ Multi-Family	☐ Addition	Residential Addit	ions			.30/sq. ft.	
	☐ Alteration/Repa	air Attached/Detached	d Garage			25/sq. ft.	
		Plan Review: Hou	ise & Garage			12/sq. ft.	
		State Permit Seal	(\$33.00 (State fee) + \$10.00)			\$43.00	
		Occupancy Permi	t (House & Garage)			.05/sq. ft.	
		Remodeling (Incl	udes Plan Review)			.20/sq. ft.	
		Ensaine Control				150.00	
		Erosion Control Decks & Porches				.20/sq. ft.	
		Storage Sheds				 	
		Re-Roof			¥1	30.00 50.00	
		Re-Siding				-	BUIN
		-	(above ground/in ground/spas)			50.00	50.00
						80.00	2
		Fence - gat	ر ۶			30.00	30.00
						-	
Required for exterior design	. appearance and					200.00	
Required for exterior design location (fences, accessory b pools, etc.)	uildings, decks, porch	es, Plan Commission/ Fee	Architectural Review Board			280.00	
		Expedited Meeting	g Fee (Nonrefundable)			100.00	
		Re-inspection Fee				75.00	
NOTES:							
Separate permits are needed f							
If any work is commenced be			fees shall be doubled.				
All calculations for square for I attest that the above inform			posed work to be performed on it. I ag	ree to co	mply with	SUB	
	and State of Wiscons	in codes applicable to the	occupancy and work stated above. I i			TOTAL:	
			BASE FEE (add to	subt	otal):		\$40.00
Applicants Signature:		Applicants Na			Permit		
		J.W.7			Total:		
OFFICE USE ONLY				1	Date		
Permit Paid By:					Date		


2023 BUILDING PERMIT LIST EXTERIOR WORK

639 First Street

PARTIAL FENCE IMPROVEMENT

Replacing approximately 55 ft length of existing fence and gate for safety/access and esthetics.

1. Replacing street-facing fence and gate located from back corner of the house to approx. 6 ft from east lot line. Replacing 6 ft high black galvanized vinyl-coated chain link with 6 ft high black powder-coated aluminum picket style (5/8" square pickets spaced 4-3/8" OC). Panels = 6'x6'. Replacing 3 ft wide chain link gate with 4-5 ft picket-style gate, matching new picket panels.





2. Move existing front 3ft wide chainlink gate to back of garage, which would require 1 additional gate post at that new location.

SIDING

GARAGE (approx. 14'x22')

Existing siding: Asphalt siding, painted white (exposed = 13" lap style). Replacing with LP Smartside, lap/cedar texture 6-6.5" exposure, to match existing house (Blue). Trimmed with LP Smart cedar texture trim, (white) to match existing house.

SIDING


'SHED' (approx. 14'x28')


Existing siding: 3 sides, plywood panel siding (vertical), batten appearance, painted light green. Backside gray asphalt siding (exposed = 13" lap style). Replacing with LP Smart panel, (vertical) batten appearance, cedar texture (medium green). Trimmed with LP Smart cedar texture trim, (white) to match house and garage trim.

*Existing doors to be replaced, including service and overhead door on garage.

Notes: NE corner of garage to SW corner of 'shed' is approx. 37 feet.

NE corner of house to front of 'shed' is approx. 56 feet (approx. 4 ft left of center).







639 FIRST

FARALLEL TO FIRST STREET

(SOUTH TACING)



(2)

639 FIRST

FRONT OF GARAGE
FACING FIRST STREET



(3)

639 FIRST

GARAGESIDE-FACING YARDERST WILL BE MATCHING HOUSE SIDING & TRIM.



639 FIRST

(H)

GARDEN "SHED" IN BACK YARD NEEDS NEW SIDING



P.O. Box 344 • 96 Russell Drive • Random Lake, WI 53075 Phone: (920) 994-4852 • Fax: (920) 994-2390

Building Permit Application

Job Location (identify e	off Court	Random	Le , WI, 53075	 >	Permit#		
Owner's Name Lovery + Kelly K	-1/x Pl	none Number 20 - 980 - 306		0		Phone Nu	ımber
Owners Address (if diff.	event from above)	20-180 700	City C		State	Zip Code	
2056 New Port	Vista Di.	N. 1	Contractor's Contact Name		WI	Phone Nu	24
Lee Kulfu Contractor's Address	istille De	cense Number - 059500476				920-	- 980-533
WTXII Com +	Ldss		City Dol 11		State	Zip Cod	e
It is the respons	sibility of the permit he	older to arrange for	appointment times when entry if the work is not visible, a re-	is avai	able for the r	equired inspect	ions If the
Use of Building	Type of Work	Sine work site of	Item		Size/Qty.	Fee Fee	Amount
Residential	New	Residence (One &			(3)	.30/sq. ft.	rimount
☐ Multi-Family	☐ Addition	Residential Additi	ions			.30/sq. ft.	
	☐ Alteration/Repair	Attached/Detached	d Garage			.25/sq. ft.	
		Plan Review: Hou	ise & Garage			.12/sq. ft.	
			(\$33.00 (State fee) + \$10.00)			\$43.00	
		Occupancy Permi	t (House & Garage)			.05/sq. ft,	
		Remodeling (Inclu	ıdes Plan Review)	- 1		.20/sq. ft,	
		Erosion Control				150.00.	
		Decks & Porches				.20/sq. ft.	
		Storage Sheds				30.00	
		Re-Roof				30.00 50.00	
		Re-Siding				50.00	
		Swimming Pools ((above ground/in ground/spas)			80.00	
		Fence				30.00	
Required for exterior design location (fences, accessory bu pools, etc.)	, appearance and uildings, decks, porches,	Plan Commission/ Fee	Architectural Review Board			280.00	
		Expedited Meeting	g Fee (Nonrefundable)			100.00	
MOTES.		Re-inspection Fee				75.00	
NOTES:							
Separate permits are needed for			·				
If any work is commenced bet All calculations for square for			fees shall be doubled.				
I attest that the above inform	nation accurately describes and State of Wisconsin co	s the property and prop	oosed work to be performed on it. I ag occupancy and work stated above. I dom Lake ordinances.	gree to co understar	omply with and that any	SUB TOTAL:	
			BASE FEE (add to	subi	total):		\$40.00
Applicants Signature;	7	Applicants Nat			Permit Total:		
OFFICE USE ONLY Permit Paid By:	T WITH WILLIAM TO PARA			Ţ	Date		



Date:

June 21, 2023

To:

Mueller Heating

Subject:

Kelly Residence

In order for this house to pass the 2009 IECC Code, the following conditions were used in figuring the heat loss:

- The <u>full</u> basement wall measured from the top of the wall down to the basement floor is insulated with <u>1" Styrofoam (R-5)</u> or greater.
- Exterior walls are insulated with **R-19** or greater.
- The ceiling is insulated with **R-50** or greater.
- Windows and patio doors are <u>Low E</u> glass with a U-value of <u>0.3</u> (R-3.33) and a minimum SHGF value of <u>0.40</u> or greater.
- TOTAL HEAT LOAD: 58,272 BTUH

Thank you,

Sebastian Arturo Barrios

Sebastian Arturo Barrios



REScheck Software Version 4.7.2

Compliance Certificate

Project

AUER STEEL SUPPLY AND HEATING - 231398 - SEBASTIAN ARTURO BARRIOS

Energy Code:

2009 IECC

Location:

Random Lake, Wisconsin

Construction Type:

Single-family

Project Type:

New Construction

Orientation:

Bldg. faces 0 deg. from North

Conditioned Floor Area: 3,976 ft2

Glazing Area

14%

Climate Zone:

6 (7474 HDD)

Permit Date:

Permit Number:

Construction Site:

Owner/Agent:

KELLY RESIDENCE

RANCH WITH EXPOSURE

Designer/Contractor: MUELLER HEATING

Compliance: Passes using performance alternative

Compliance: 3.0% Better Than Code

NOTE: Slab-on-grade tradeoffs are no longer considered in the UA or performance compliance path in REScheck. Each slab-ongrade assembly in the specified climate zone must meet the minimum energy code insulation R-value and depth requirements.

Envelope Assemblies

Assembly	Gross Area or Perimeter	Cavity R-Value	Cont. R-Value	Prop. U-Factor	Req. U-Factor	Prop. UA	Req. UA
Ceiling 1: Raised or Energy Truss	1,988	50.0	0.0	0.020	0.026	40	52
Wall 1: Wood Frame, 16" o.c. Orientation: Front	700	19.0	0.0	0.060	0.057	35	33
Window 1: Metal Frame with Thermal Break:Double Pane with Low-E SHGC: 0.40 Orientation: Front	83			0.300	0.350	25	29
Door 1: Solid Orientation: Front	40			0.200	0.350	8	14
Wall 2: Wood Frame, 16" o.c. Orientation: Right side	420	19.0	0.0	0.060	0.057	23	22
Door 2: Glass SHGC: 0.40 Orientation: Right side	40			0.300	0.350	12	14
Wall 3: Wood Frame, 16" o.c. Orientation: Back	700	19.0	0.0	0.060	0.057	30	28
Window 2: Metal Frame with Thermal Break:Double Pane with Low-E SHGC: 0.40 Orientation: Back	161			0.300	0.350	48	56
	40			0.300	0.350	12	14

Project Title: AUER STEEL SUPPLY AND HEATING - 231398 - SEBASTIAN ARTURO BARRIOS

Data filename: Untitled.rck

Report date: 06/21/23

Page 1 of 7

Assembly	Gross Area or Perimeter	Cavity R-Value	Cont. R-Value	Prop. U-Factor	Req. U-Factor	Prop. UA	Req. UA
Wall 4: Wood Frame, 16" o.c. Orientation: Left side	420	19.0	0.0	0.060	0.057	25	23
Window 3: Metal Frame with Thermal Break:Double Pane with Low-E SHGC: 0.40 Orientation: Left side	10			0.300	0.350	3	4
Basement Wall 1: Solid Concrete or Masonry Orientation: Front Wall height: 8.0' Depth below grade: 7.3' Insulation depth: 8.0'	560	0.0	5.0	0.087	0.050	49	28
Basement Wall 2: Solid Concrete or Masonry Orientation: Right side Wall height: 8.0' Depth below grade: 7.3' Insulation depth: 8.0'	160	0.0	5.0	0.087	0.050	14	8
Basement Wall 3: Solid Concrete or Masonry Orientation: Left side Wall height: 8.0' Depth below grade: 7.3' Insulation depth: 8.0'	208	0.0	5.0	0.087	0.050	18	10
Basement Wall 4: Solid Concrete or Masonry Orientation: Right side Wall height: 3.0' Depth below grade: 2.3' Insulation depth: 3.0'	66	0.0	5.0	0.124	0.050	8	3
Basement Wall 5: Solid Concrete or Masonry Orientation: Back Wall height: 3.0' Depth below grade: 2.3' Insulation depth: 3.0'	210	0.0	5.0	0.124	0.050	26	11
Basement Wall 6: Solid Concrete or Masonry Orientation: Left side Wall height: 3.0' Depth below grade: 2.3' Insulation depth: 3.0'	48	0.0	5.0	0.124	0.050	6	2
Wall 5: Wood Frame, 16" o.c. Orientation: Right side	110	19.0	0.0	0.060	0.057	6	5
Window 4: Metal Frame with Thermal Break:Double Pane with Low-E SHGC: 0.40 Orientation: Right side	15			0.300	0.350	5	5
Wall 6: Wood Frame, 16" o.c. Orientation: Back	350	19.0	0.0	0.060	0.057	18	17
Window 5: Metal Frame with Thermal Break:Double Pane with Low-E SHGC: 0.40 Orientation: Back	45			0.300	0.350	14	16
Wall 7: Wood Frame, 16" o.c. Orientation: Left side	80	19.0	0.0	0.060	0.057	5	5

Compliance Statement: The proposed building design described here is consistent with the building plans, specifications, and other calculations submitted with the permit application. The proposed building has been designed to meet the 2009 IECC requirements in REScheck Version 4.7.2 and to comply with the mandatory requirements listed in the REScheck Inspection Checklist.

Sebastian Arturo Barrios - Heat Calc Technician

Sebastian Arturo Barrios Signature 6/21/23

Name - Title

Project Notes:

TOTAL HEAT LOAD: 58,272 BTUH

Project Title: AUER STEEL SUPPLY AND HEATING - 231398 - SEBASTIAN ARTURO BARRIOS Data filename: Untitled.rck

Report date: 06/21/23

Page 2 of 7



REScheck Software Version 4.7.2

Inspection Checklist

Energy Code: 2009 IECC

Requirements: 0.0% were addressed directly in the REScheck software

Text in the "Comments/Assumptions" column is provided by the user in the REScheck Requirements screen. For each requirement, the user certifies that a code requirement will be met and how that is documented, or that an exception is being claimed. Where compliance is itemized in a separate table, a reference to that table is provided.

Section # & Req.ID	Pre-Inspection/Plan Review	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
103.2 [PR1] ¹	Construction drawings and documentation demonstrate energy code compliance for the building envelope.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
103.2, 403.7 [PR3] ¹	Construction drawings and documentation demonstrate energy code compliance for lighting and mechanical systems. Systems serving multiple dwelling units must demonstrate compliance with the commercial code.			□Complies □Does Not □Not Observable □Not Applicable	
403.6 [PR2] ²	Heating and cooling equipment is sized per ACCA Manual S based on loads per ACCA Manual J or other approved methods.	Heating: Btu/hr Cooling: Btu/hr	Heating: Btu/hr Cooling: Btu/hr	□Complies □Does Not □Not Observable □Not Applicable	

Additional Comments/Assumptions:

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Project Title: AUER STEEL SUPPLY AND HEATING - 231398 - SEBASTIAN ARTURO BARRIOS Data filename: Untitled.rck

Page 3 of 7

Section # & Req.ID	Foundation Inspection	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
402.1.1 [FO4] ¹	Conditioned basement wall insulation R-value. Where interior insulation is used, verification may need to occur during Insulation Inspection. Not required in warm-humid locations in Climate Zone 3.	R	R	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.2 [FO5] ¹	Conditioned basement wall insulation installed per manufacturer's instructions.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
402.2.7 [FO6] ¹	Conditioned basement wall insulation depth of burial or distance from top of wall.	ft	ft	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303,2.1 [F011] ²	A protective covering is installed to protect exposed exterior insulation and extends a minimum of 6 in. below grade.			□Complies □Does Not □Not Observable □Not Applicable	
403.8 (FO12) ²	Snow- and ice-melting system controls installed.			□Complies □Does Not □Not Observable □Not Applicable	

1 High Impact (Tier 1)	2	Medium Impact (Tier 2)	3	Low Impact (Tier 3)	
					_

Project Title: AUER STEEL SUPPLY AND HEATING - 231398 - SEBASTIAN ARTURO BARRIOS Data filename: Untitled.rck

Section # & Req.ID	Framing / Rough-In Inspection	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
402.1.1, 402.3.4 [FR1] ¹	Door U-factor.	U	U	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
402.1.1, 402.3.1, 402.3.3, 402.5 [FR2] ¹	Glazing U-factor (area-weighted average).	U	U	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.1.3 [FR4] ¹	U-factors of fenestration products are determined in accordance with the NFRC test procedure or taken from the default table.			Complies Does Not Not Observable Not Applicable	2
402.4.4 [FR20] ¹	Fenestration that is not site built is listed and labeled as meeting AAMA/WDMA/CSA 101/I.S.2/A440 or has infiltration rates per NFRC 400 that do not exceed code limits.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
402.4.5 [FR16] ²	IC-rated recessed lighting fixtures sealed at housing/interior finish and labeled to indicate ≤2.0 cfm leakage at 75 Pa.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
405.2 [FR25] ¹	All ducts in unconditioned spaces or outside the building envelope are insulated to ≥R-6.	R	R	□Complies □Does Not □Not Observable □Not Applicable	
403.2.2 [FR13] ¹	All joints and seams of air ducts, air handlers, filter boxes, and building cavities used as return ducts are sealed.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	2 2 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
403.2.3 [FR15] ³	Building cavities are not used for supply ducts.			□Complies □Does Not □Not Observable □Not Applicable	
403.3 [FR17] ²	HVAC piping conveying fluids above 105 °F or chilled fluids below 55 °F are insulated to ≥R- 3.	R	R	□Complies □Does Not □Not Observable □Not Applicable	
403.4 [FR18] ²	Circulating service hot water pipes are insulated to R-2.	R	R	□Complies □Does Not □Not Observable □Not Applicable	
403.5 [FR19] ²	Automatic or gravity dampers are installed on all outdoor air intakes and exhausts.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	

1 High Impact (Tier 1) 2 Mediu	1 Impact (Tier 2) 3 Low Impact (Tier 3)
--------------------------------	---

Section # & Req.ID	Insulation Inspection	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
303.1 [IN13] ²	All installed insulation is labeled or the installed R-values provided.	a A Shadin		□Complies □Does Not □Not Observable □Not Applicable	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
402.1.1, 402.2.4, 402.2.5 [IN3] ¹	Wall insulation R-value. If this is a mass wall with at least ½ of the wall insulation on the wall exterior, the exterior insulation requirement applies.	R Wood Mass Steel	R Wood Mass Steel	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.2 [IN4] ¹	Wall insulation is installed per manufacturer's instructions.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Section # & Req.ID	Final Inspection Provisions	Plans Verified Value	Field Verified Value	Complies?	Comments/Assumptions
402.1.1, 402.2.1, 402.2.2 [FI1] ¹	Celling insulation R-value. Where > R-30 is required, R-30 can be used if insulation is not compressed at eaves. R-30 may be used for 500 ft ² or 20% (whichever is less) where sufficient space is not available.	R Wood Steel	R Wood Steel	□Complies □Does Not □Not Observable □Not Applicable	See the Envelope Assemblies table for values.
303.1.1.1, 303.2 [FI2] ¹	Ceiling insulation installed per manufacturer's instructions. Blown insulation marked every 300 ft ² .			□Complies □Does Not □Not Observable □Not Applicable	
402.4.2, 402.4.2.1 [FI17] ¹	Building envelope tightness verified by blower door test result of <7 ACH at 50 Pa. This requirement may instead be met via visual inspection, in which case verification may need to occur during Insulation inspection.	ACH 50 =	ACH 50 =	□Complies □Does Not □Not Observable □Not Applicable	
403.2.2 [FI4] ¹	Post construction duct tightness test result of ≤8 cfm to outdoors, or ≤12 cfm across systems. Or, rough-in test result of ≤6 cfm across systems or ≤4 cfm without air handler. Rough-in test verification may need to occur during Framing Inspection.	cfm	cfm	□Complies □Does Not □Not Observable □Not Applicable	
403.6 [FI5] ¹	Heating and cooling equipment type and capacity as per plans.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
403.1.1 [FI9] ²	Programmable thermostats installed on forced air furnaces.			☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
403.1.2 [FI10] ²	Heat pump thermostat installed on heat pumps.	A 1.0	Victoria de la composição de la composiç	☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	
403.4 [FI11]² ⊌	Circulating service hot water systems have automatic or accessible manual controls.			□Complies □Does Not □Not Observable □Not Applicable	
401.3 [Fi7]?	Compliance certificate posted.			□Complies □Does Not □Not Observable □Not Applicable	
303.3 [FI18] ³	Manufacturer manuals for mechanical and water heating equipment have been provided.			□Complies □Does Not □Not Observable □Not Applicable	

1 High Impact (Tier 1)	2	Medium Impact (Tier 2)	3	Low Impact (Tier 3)



2009 IECC Energy Efficiency Certificate

Date:

Insulation Rating	R-Value	
Above-Grade Wall	19.00	
Below-Grade Wall	5.00	
Floor	0.00	
Celling / Roof	50.00	
Ductwork (unconditioned spaces):	-	
Glass & Door Rating	U-Factor	SHGC

Window	0.30	0.40
Door	0.20	0.40
Heating & Cooling Equipment	Efficiency	
Heating System:		
Cooling System:	2	
Water Heater:		
是是一种的特别的。可是对他的现在分词是不是有		


Name:

Comments

Heating Equipmen	nt Sizing Sum	mary
General Information		
Project Name/Address	KELLY RESIDENCE	A VALUE
County	SHEBOYGAN	
Design Temperature	-15	Degrees (F)
"Your UA" from ResCheck	430	UA
Conditioned Floor Area	3976	SqFt
Average Wall Height	9	Ft
Infiltration Rate	0.30	ACH (typ 0.50)
Equipment Oversizing Factor	10	%
Load Summary		
Conductive Losses	36550	Btu/Hr
Infiltration Losses	16425	Btu/Hr
Oversizing Factor Losses	5297	Btu/Hr
Total Building Heating Load	58272	Btu/Hr
Enter Items in Yellow to get your to	otal Heat Loss. Pi	rint and attach

Enter Items in Yellow to get your total Heat Loss. Print and attach with your completed ResCheck Form

Plat of Survey for Todd Kultgen



Homeland Surveying, LLC 2079 Cold Springs Rd. Saukville, WI 53080 Phone:(262)689-6885 Email: homeland2079@gmail.com

Professional Land Surveyo